

# Oil Field Environmental Incident Summary

**Incident:** 20150406144403 **Date/Time of Notice:** 04/06/2015 14:44

**Responsible Party:** DENBURY ONSHORE, LLC

**Well Operator:** DENBURY ONSHORE, LLC

**Well Name:** CROAK A 1

**Field Name:** SOUTH WESTHOPE

**Well File #:** 1954

**Date Incident:** 4/6/2015 **Time Incident:** 09:45

**Facility ID Number:**

**County:** BOTTINEAU

**Twp:** 162

**Rng:** 80

**Sec:** 25

**Qtr:** NE NW

**Location Description:**

**Submitted By:** Josh Cuppy

**Received By:**

**Contact Person:** Richard Larson  
5320 LEGACY DR  
PLANO, TX 75024-3127

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1.5 Mile

**Distance Nearest Water Well:** 1.5 Mile

**Type of Incident:** Vessel Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels
Brine	40	Barrels	40	Barrels	40	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/25/2016

**Clean Up Concluded:** 9/16/2015

**Risk Evaluation:**

None

**Areal Extent:**

COntained within dike.

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Shut in vessel. Vac truck was dispatched to begin cleanup.

**Wastes Disposal Location:** Landfill

**Agencies Involved:**

**Updates**

---

**Date:** 4/6/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a vessel leak, remained on location within the dike according to the report. NDIC retains oversight.